

# MET 237 COMPUTER NUMERICAL CONTROL

Eng. Ali Almandeel  
Spring 2010  
Programming Linear Profiles [ Milling]

## 7 | Linear Interpolation Commands

- Linear Interpolation (G01).

**G01** is a straight line feed movement and the lines can be **horizontal**, **vertical**, or at any **angle**.




Figure 7 Linear interpolation.